

BLACK SHIELD CHECK LIST (as of 14 Jul 67)

Page 2

H-Minus	25X1A ACTION	DOI	RESP INDV	TIME DUE(Z)	TIME DUE(L)	TIME DONE(L)	DONE BY (Initials)
-10:00	Send [REDACTED] (Terminal wx fcsts)	B-5		13/1610	14/0110	0051	JY
-9:00	Rev [REDACTED] GO-NO GO wx fcsts)	B-11		1710	0210	0100	JY
25X1A -9:00	Give [REDACTED] input to Msn Coord	B-23		1710	0210	2330	JY
-8:00	Send [REDACTED] (thru L-hr, if reqd)	B-16		1810	0310		
	Annotate tanker DD Forms 175	B-24		CANCELLED	0257	R-90	[Signature]
	Brief tankers [REDACTED]	B-24		2125 2110	0625 0610		
25X1A -4:00	Send [REDACTED] (Terminal wx fcsts)	B-5		2210	0710		
-4:00	Send [REDACTED] (Met Watch obs)	B-18		2210	0710		
	Brief tankers [REDACTED]	B-24		2245 2230	0745 0730		
-3:30	Brief pilots and ops staff	B-20		2240	0740		
25X1A	Brief tankers [REDACTED]	B-24		2245 2300	0825 0800		
-3:00	Rev [REDACTED] Amend (GO/NO GO fcsts)	B-11		2310	0810		
-3:00	Rev Letdown Plates from DCO	B-14		2310	0810		
-3:00	Enter fcsts on Letdown Plates	B-14		2310	0810		
-2:30	Msn Obsvr to CP; posts data	B-13		2340	0840		
25X1A -2:00	Rev [REDACTED] (Wx Scout reports)	B-22		14/0010	0910		
	Pick up APT pictures	B-10		0000 or ASAP	0900 or ASAP		
-1:40	Msn Fcstr to CP; Obsvr to wx str	B-13		0030	0930		
-1:35	Letdown plate fcsts to pilots (Notify Mission Coordinator)	B-14		0035	0935		
-1:30	Notify DCO (If need to rebrief pilots)	B-20		0040	0940		
-1:10	Rebrief pilots if necessary	B-20		0100	1000		
L-Plus	Landing time: Z L						
+0:15	Return Met Watch to wx station	B-13					
+0:15	Start debriefing form	B-15					
+0:45	Attend pilot debriefing	B-15					
ASAP	Give R-118 input to DCOM Coord after debriefing	B-15		ASAP	ASAP		
+24:00	Turn in Msn Wx File to Intell	B-17					

25X1A

Approved For Release 2001/03/02 : CIA-RDP69B00041R002300060003-5

Approved For Release 2001/03/02 : CIA-RDP69B00041R002300060003-5